

## **PART 1 OF 2**

**IN THE UNITED STATES BANKRUPTCY COURT  
FOR THE DISTRICT OF DELAWARE**

In re:	)	Chapter 11
	)	
	)	Case No. 01-01139 (JKF)
W.R. Grace & Co., et al.,	)	(Jointly Administered)
	)	
Debtors.	)	Re: Docket No. 13406
	)	

---

**CLAIMANTS REPRESENTED  
BY DIES & HILE, L.L.P.'S  
SUBMISSION OF EXPERT REPORTS  
FROM CONSTRUCTION INSPECTORS, INC.,  
GOBBELL HAYS PARTNERS, INC., MARTIN BENNETT OF  
MATERIALS ANALYTICAL SERVICES, INC., ANDREW GRAY OF  
OREGON STATE UNIVERSITY, STEVE PELKEY OF THE UNIVERSITY OF  
OREGON, GREGG TAYLOR OF SOUTHERN OREGON UNIVERSITY, AND  
RUBEN TORRES OF PORTLAND STATE UNIVERSITY, REGARDING ADJUDICATION  
OF THE LACK OF HAZARD ISSUE AS DESCRIBED IN THE 15TH OMNIBUS OBJECTIONS**

In accordance with the Court's Amended Order Setting Various Deadlines Regarding Objections to Asbestos Property Damage Claims, dated October 13, 2006 (D.I. 13406), Claimants represented by the Law Firm of Dies & Hile, L.L.P. (the "D&H PD Claimants")<sup>1</sup> hereby submit their Submission of Expert Reports Regarding Adjudication of the Lack of Hazard Issue as Described in the 15<sup>th</sup> Omnibus Objections, and state as follows:

**I.**

On December 7, 2006, the D&H PD Claimants filed their Preliminary Designation of Fact and Expert Witnesses Regarding Adjudication of Lack of Hazard Issue as Described in the

---

<sup>1</sup> The Asbestos Property Damage Claimants Represented by the Law Firm of Dies & Hile, L.L.P., on whose behalf this Submission of Expert Reports Regarding the Adjudication of the Lack of Hazard Issue as Described in the 15<sup>th</sup> Omnibus Objections is served, include the following: State of Arizona; State of Arkansas; State of Connecticut; State of Oklahoma; State of Oregon; City of Amarillo, Texas; City of Houston, Texas; Coleman Housing Authority, El Paso County, Texas; Harlingen Housing Authority; Sabine River Authority of Texas; City of Phoenix, Arizona; City of Tucson, Arizona; Maricopa County, Arizona; Cook County, Illinois; City of Eugene, Oregon; Eastern Oregon University; Oregon Health & Science University; Oregon State University; Portland State University; Southern Oregon University; University of Oregon; Western Oregon University; Six Hundred Building Ltd.; BNC Forum LP Texas Limited Partnership; and EPEC Realty, Inc.

15<sup>th</sup> Omnibus Objections (the “Designation of Fact and Expert Witnesses”; D.I. 13744). In this pleading the D&H PD Claimants identified their lack of hazard expert and fact witnesses, and the subject matter of their testimony. The D&H PD Claimants hereby fully incorporate by reference all matters set forth herein, including the exhibits and attachments to said Designation of Fact and Expert Witnesses.

## **II.**

On December 21, 2006, the D&H PD Claimants filed Claimants Represented by the Law Firm of Dies & Hile, L.L.P.’s Submission of Expert Reports, and Identification of Any Additional Fact Witnesses and General Subject Matter of Testimony Regarding the Schedule for the Adjudication of Product Identification Issues, as Described in the 15<sup>th</sup> Omnibus Objections. In this pleading the D&H PD Claimants submitted their expert reports and/or other documentation regarding the issue of product identification. The D&H PD Claimants hereby fully incorporate by reference all matters set forth herein.

## **III.**

On December 22, 2006, the D&H PD Claimants filed their Claimants’ Represented by the Law Firm of Dies & Hile, L.L.P. Supplemental Designation of Fact and Expert Witnesses Regarding Adjudication of Lack of Hazard Issue as Described in the 15<sup>th</sup> Omnibus Objections (the “Designation of Fact and Expert Witnesses”; D.I. 13744). In this pleading the D&H PD Claimants identified supplemental lack of hazard expert and fact witnesses, and the subject matter of their testimony. The D&H PD Claimants hereby fully incorporate by reference all matters set forth herein.

## **IV.**

The D&H PD Claimants have filed with the Proof of Claim for each building inspection reports, surveys, memorandums, notices filed with state agencies, contracts and other documents,

or summaries thereof, that refer or relate to the inspection, management and/or abatement of acoustical plaster or fireproofing materials installed in Claimants' buildings. For certain claims, other documentation includes historical construction documents, plans and specifications, laboratory analysis reports, product advertisements, brochures, and/or other similar documents. These documents or summaries were either filed with the original proofs of claim or subsequently filed as supplemental information or summaries. The D&H PD Claimants' experts may rely upon the facts and underlying data contained in these documents as a basis for opinions or inferences regarding lack of hazard, as such facts and data are of a type reasonably relied upon by experts in their field in forming opinions or inference upon the subject of their testimony.

All of such documents referred to hereinabove that have not been previously provided to counsel for Debtors will be provided to them upon request. The D&H PD Claimants herewith incorporate by reference all of these documents which have been, or will be, filed in the claim files for the below referenced claims.<sup>2</sup> The D&H PD Claimants reserve the right to introduce such during trial of the lack of hazard issue.

Further, the D&H PD Claimants have separately filed a submission of other expert reports regarding the lack of hazard issue, and this submission is not intended to supersede or amend such other expert submission. Rather, this submission supplements and separately identifies those additional expert witnesses and reports which are specific to the following claims:

---

<sup>2</sup> Counsel for the D&H PD Claimants met with representatives of the Debtors on September 20, 2006, and has discussed certain of Debtors' objections. Counsel for the D&H PD Claimants agreed to provide, and did provide, additional documentation with regard to some claims to counsel for Debtors and is continuing to do so in an attempt to reach resolution with Debtors concerning such objections.

**A. STATE OF ARIZONA:**

<b>CLAIM #</b>	<b>ENTITY/BUILDING NAME</b>	<b>DESCRIPTION OF REPORT</b>
12721	STATE OF ARIZONA/ Veterans Memorial Coliseum	<p>Construction Inspectors, Inc. <i>Chain of Custody Log(s)</i> and <i>Bulk Sample Data Sheet(s)</i>, which includes the sample and material location, and a sample location of the area from which a bulk sample was taken. Filed with Proof of Claim.</p> <p>12/28/2006 Gobbell Hays Partners, Inc. Report styled <i>Inspection of Asbestos-Containing Surface Treatment Materials</i> prepared by Wade Anderson that includes description of building, location and quantity of Grace ACM and hazard assessment for Grace ACM in this building. Filed as supplemental claims information.</p> <p>01/7/2007 Construction Inspectors, Inc. Report styled <i>Inspection of Asbestos-Containing Surface Treatment Materials</i> prepared by John Mertian that includes description of building, surveys of building, and location, types and quantity of ACM. Filed as supplemental claims information.</p>
12692	STATE OF ARIZONA/ Senate Building	<p>Construction Inspectors, Inc. <i>Chain of Custody Log(s)</i> and <i>Bulk Sample Data Sheet(s)</i>, which includes the sample and material location, and a sample location of the area from which a bulk sample was taken. Filed with Proof of Claim.</p> <p>12/29/2006 Construction Inspectors, Inc. Report styled <i>Inspection of Asbestos-Containing Surface Treatment Materials</i> prepared by Tom Manning that includes description of building, surveys of building, and location, types and quantity of ACM. Filed as supplemental claims information.</p>
12693	STATE OF ARIZONA/ House of Representatives	<p>Construction Inspectors, Inc. <i>Chain of Custody Log(s)</i> and <i>Bulk Sample Data Sheet(s)</i>, which includes the sample and material location, and a sample location of the area from which a bulk sample was taken. Filed with Proof of Claim.</p> <p>12/29/2006 Construction Inspectors, Inc. Report styled <i>Inspection of Asbestos-Containing</i></p>

CLAIM #	ENTITY/BUILDING NAME	DESCRIPTION OF REPORT
		<i>Surface Treatment Materials</i> prepared by Tom Manning that includes description of building, surveys of building, and location, types and quantity of ACM. Filed as supplemental claims information.
12699	STATE OF ARIZONA/ DES Office	Construction Inspectors, Inc. <i>Chain of Custody Log(s)</i> and <i>Bulk Sample Data Sheet(s)</i> , which includes the sample and material location, and a sample location of the area from which a bulk sample was taken. Filed with Proof of Claim.  12/29/2006 Construction Inspectors, Inc. Report styled <i>Inspection of Asbestos-Containing Surface Treatment Materials</i> prepared by Tom Manning that includes description of building, surveys of building, and location, types and quantity of ACM. Filed as supplemental claims information.
12694	STATE OF ARIZONA/ Corrections Facility	Construction Inspectors, Inc. <i>Chain of Custody Log(s)</i> and <i>Bulk Sample Data Sheet(s)</i> , which includes the sample and material location, and a sample location of the area from which a bulk sample was taken. Filed with Proof of Claim.  12/18/2006 Gobbell Hays Partners, Inc. Report styled <i>Inspection of Asbestos-Containing Surface Treatment Materials</i> prepared by Wade Anderson that includes description of building, location and quantity of Grace ACM and hazard assessment for Grace ACM in this building. Filed as supplemental claims information.
12695	STATE OF ARIZONA/ Historical Society Museum	Construction Inspectors, Inc. <i>Chain of Custody Log(s)</i> and <i>Bulk Sample Data Sheet(s)</i> , which includes the sample and material location, and a sample location of the area from which a bulk sample was taken. Filed with Proof of Claim.  12/20/2006 Gobbell Hays Partners, Inc. Report styled <i>Inspection of Asbestos-Containing Surface Treatment Materials</i> prepared by Wade Anderson that includes description of building, location and quantity of Grace ACM and hazard assessment for Grace ACM in this building. Filed as supplemental claims information.

CLAIM #	ENTITY/BUILDING NAME	DESCRIPTION OF REPORT
		information.  01/09/07 Expert Report by Martin R. Bennett, Materials Analytical Services, LLC, which includes Qualifications, Field Notes, Background and General Observations, AHERA Assessment, and Contamination Assessment for asbestos-containing, surface treatment materials ("ACSTM") in this building. The report also includes the results of micro-vacuum settled dust samples. This report has been filed as supplemental claims information with the Claims Facility.
12696	STATE OF ARIZONA/ Executive Tower	Construction Inspectors, Inc. <i>Chain of Custody Log(s)</i> and <i>Bulk Sample Data Sheet(s)</i> , which includes the sample and material location, and a sample location of the area from which a bulk sample was taken. Filed with Proof of Claim.
12697	STATE OF ARIZONA/ Arizona State Hospital – Cholla Hall	Construction Inspectors, Inc. <i>Chain of Custody Log(s)</i> and <i>Bulk Sample Data Sheet(s)</i> , which includes the sample and material location, and a sample location of the area from which a bulk sample was taken. Filed with Proof of Claim.
12720	STATE OF ARIZONA/ Arizona State Hospital – Dietary Building	Construction Inspectors, Inc. <i>Chain of Custody Log(s)</i> and <i>Bulk Sample Data Sheet(s)</i> , which includes the sample and material location, and a sample location of the area from which a bulk sample was taken. Filed with Proof of Claim.
12698	STATE OF ARIZONA/ Arizona State Hospital – General Services	Construction Inspectors, Inc. <i>Chain of Custody Log(s)</i> and <i>Bulk Sample Data Sheet(s)</i> , which includes the sample and material location, and a sample location of the area from which a bulk sample was taken. Filed with Proof of Claim.  12/18/2006 Gobbell Hays Partners, Inc. Report styled <i>Inspection of Asbestos-Containing Surface Treatment Materials</i> prepared by Wade Anderson that includes description of building, location and quantity of Grace ACM and hazard assessment for Grace ACM in this building. Filed as supplemental claims information.

**B. STATE OF ARKANSAS:**

<b>CLAIM #</b>	<b>ENTITY/BUILDING NAME</b>	<b>DESCRIPTION OF REPORT</b>
12689	STATE OF ARKANSAS/ Alexander Human Dev. Cntr. – Bond Building	<p>01/05/2003 Construction Inspectors, Inc. <i>Chain of Custody Log(s)</i> and <i>Bulk Sample Data Sheet(s)</i>, which includes the sample and material location, and a sample location of the area from which a bulk sample was taken. Filed with Proof of Claim.</p> <p>10/06/2006 Construction Inspectors, Inc. Report styled <i>Inspection of Asbestos-Containing Surface Treatment Materials</i> prepared by Tom Manning that includes description of building, surveys of building, and location, types and quantity of ACM. Filed as supplemental claims information.</p>
12686	STATE OF ARKANSAS/ Arkansas Health Center- Mental Health Services – Maintenance Bldg. No. 18	<p>Construction Inspectors, Inc. <i>Chain of Custody Log(s)</i> and <i>Bulk Sample Data Sheet(s)</i>, which includes the sample and material location, and a sample location of the area from which a bulk sample was taken. Filed with Proof of Claim.</p> <p>12/18/2006 and 12/26/2006 Gobbell Hays Partners, Inc. Reports styled <i>Inspection of Asbestos-Containing Surface Treatment Materials</i> prepared by Wade Anderson that includes description of building, location and quantity of Grace ACM and hazard assessment for Grace ACM in this building. Filed as supplemental claims information.</p> <p>01/09/07 Expert Report by Martin R. Bennett, Materials Analytical Services, LLC, which includes Qualifications, Field Notes, Background and General Observations, AHERA Assessment, and Contamination Assessment for ACSTM in this building. The report also includes the results of micro-vacuum settled dust samples. This report has been filed as supplemental claims information with the Claims Facility.</p>
12678	STATE OF ARKANSAS/ Arkansas State Hospital – Administration Bldg.	Construction Inspectors, Inc. <i>Chain of Custody Log(s)</i> and <i>Bulk Sample Data Sheet(s)</i> , which includes the sample and material location, and a

CLAIM #	ENTITY/BUILDING NAME	DESCRIPTION OF REPORT
		<p>sample location of the area from which a bulk sample was taken. Filed with Proof of Claim.</p> <p>1/03/07 Gobbell Hays Partners, Inc. Report styled <i>Inspection of Asbestos-Containing Surface Treatment Materials</i> prepared by Wade Anderson that includes description of building, location and quantity of Grace ACM and hazard assessment for Grace ACM in this building. Filed as supplemental claims information.</p> <p>01/09/07 Expert Report by Martin R. Bennett, Materials Analytical Services, LLC, which includes Qualifications, Field Notes, Background and General Observations, AHERA Assessment, and Contamination Assessment for ACSTM in this building. The report also includes the results of micro-vacuum settled dust samples. This report has been filed as supplemental claims information with the Claims Facility.</p>
12736	STATE OF ARKANSAS/ Arkansas State Hospital – Admissions Bldg.	<p>12/23/2002 Construction Inspectors, Inc. <i>Chain of Custody Log(s)</i> and <i>Bulk Sample Data Sheet(s)</i>, which includes the sample and material location, and a sample location of the area from which a bulk sample was taken. Filed with Proof of Claim.</p> <p>1/03/07 Gobbell Hays Partners, Inc. Report styled <i>Inspection of Asbestos-Containing Surface Treatment Materials</i> prepared by Wade Anderson that includes description of building, location and quantity of Grace ACM and hazard assessment for Grace ACM in this building. Filed as supplemental claims information.</p> <p>01/09/07 Expert Report by Martin R. Bennett, Materials Analytical Services, LLC, which includes Qualifications, Field Notes, Background and General Observations, AHERA Assessment, and Contamination Assessment for ACSTM in this building. The report also includes the results of micro-vacuum settled</p>

CLAIM #	ENTITY/BUILDING NAME	DESCRIPTION OF REPORT
		dust samples. This report has been filed as supplemental claims information with the Claims Facility.
12677	STATE OF ARKANSAS/ Arkansas State Hospital – Canteen Bldg.	<p>12/23/2002 Construction Inspectors, Inc. <i>Chain of Custody Log(s)</i> and <i>Bulk Sample Data Sheet(s)</i>, which includes the sample and material location, and a sample location of the area from which a bulk sample was taken. Filed with Proof of Claim.</p> <p>1/03/07 Gobbell Hays Partners, Inc. Report styled <i>Inspection of Asbestos-Containing Surface Treatment Materials</i> prepared by Wade Anderson that includes description of building, location and quantity of Grace ACM and hazard assessment for Grace ACM in this building. Filed as supplemental claims information.</p> <p>01/09/07 Expert Report by Martin R. Bennett, Materials Analytical Services, LLC, which includes Qualifications, Field Notes, Background and General Observations, AHERA Assessment, and Contamination Assessment for ACSTM in this building. The report also includes the results of micro-vacuum settled dust samples. This report has been filed as supplemental claims information with the Claims Facility.</p>
12680	STATE OF ARKANSAS/ Arkansas State Hospital – Hendrix Hall	12/23/2002 Construction Inspectors, Inc. <i>Chain of Custody Log(s)</i> and <i>Bulk Sample Data Sheet(s)</i> , which includes the sample and material location, and a sample location of the area from which a bulk sample was taken. Filed with Proof of Claim.
12676	STATE OF ARKANSAS/ Arkansas State Hospital – Nursing Administration Bldg.	<p>12/23/2002 Construction Inspectors, Inc. <i>Chain of Custody Log(s)</i> and <i>Bulk Sample Data Sheet(s)</i>, which includes the sample and material location, and a sample location of the area from which a bulk sample was taken. Filed with Proof of Claim.</p> <p>1/03/07 Gobbell Hays Partners, Inc. Report styled <i>Inspection of Asbestos-Containing Surface Treatment Materials</i> prepared by</p>

CLAIM #	ENTITY/BUILDING NAME	DESCRIPTION OF REPORT
		<p>Wade Anderson that includes description of building, location and quantity of Grace ACM and hazard assessment for Grace ACM in this building. Filed as supplemental claims information.</p> <p>01/09/07 Expert Report by Martin R. Bennett, Materials Analytical Services, LLC, which includes Qualifications, Field Notes, Background and General Observations, AHERA Assessment, and Contamination Assessment for ACSTM in this building. The report also includes the results of micro-vacuum settled dust samples. This report has been filed as supplemental claims information with the Claims Facility.</p>
12737	STATE OF ARKANSAS/ Arkansas State Hospital – Rodgers Hall (Central Arkansas Community Punishment Center)	12/31/2002 Construction Inspectors, Inc. <i>Chain of Custody Log(s)</i> and <i>Bulk Sample Data Sheet(s)</i> , which includes the sample and material location, and a sample location of the area from which a bulk sample was taken. Filed with Proof of Claim.
12732	STATE OF ARKANSAS/ Arkansas State Hospital – Unit No. 1	<p>12/23/2002 Construction Inspectors, Inc. <i>Chain of Custody Log(s)</i> and <i>Bulk Sample Data Sheet(s)</i>, which includes the sample and material location, and a sample location of the area from which a bulk sample was taken. Filed with Proof of Claim.</p> <p>1/03/07 Gobbell Hays Partners, Inc. Report styled <i>Inspection of Asbestos-Containing Surface Treatment Materials</i> prepared by Wade Anderson that includes description of building, location and quantity of Grace ACM and hazard assessment for Grace ACM in this building. Filed as supplemental claims information.</p> <p>01/09/07 Expert Report by Martin R. Bennett, Materials Analytical Services, LLC, which includes Qualifications, Field Notes, Background and General Observations, AHERA Assessment, and Contamination Assessment for ACSTM in this building. The report also includes the results of micro-vacuum settled</p>

CLAIM #	ENTITY/BUILDING NAME	DESCRIPTION OF REPORT
		dust samples. This report has been filed as supplemental claims information with the Claims Facility.
12733	STATE OF ARKANSAS/ Arkansas State Hospital – Unit No. 2	<p>12/23/2002 Construction Inspectors, Inc. <i>Chain of Custody Log(s)</i> and <i>Bulk Sample Data Sheet(s)</i>, which includes the sample and material location, and a sample location of the area from which a bulk sample was taken. Filed with Proof of Claim.</p> <p>1/03/07 Gobbell Hays Partners, Inc. Report styled <i>Inspection of Asbestos-Containing Surface Treatment Materials</i> prepared by Wade Anderson that includes description of building, location and quantity of Grace ACM and hazard assessment for Grace ACM in this building. Filed as supplemental claims information.</p> <p>01/09/07 Expert Report by Martin R. Bennett, Materials Analytical Services, LLC, which includes Qualifications, Field Notes, Background and General Observations, AHERA Assessment, and Contamination Assessment for ACSTM in this building. The report also includes the results of micro-vacuum settled dust samples. This report has been filed as supplemental claims information with the Claims Facility.</p>
12734	STATE OF ARKANSAS/ Arkansas State Hospital – Unit No. 3	<p>12/23/2002 Construction Inspectors, Inc. <i>Chain of Custody Log(s)</i> and <i>Bulk Sample Data Sheet(s)</i>, which includes the sample and material location, and a sample location of the area from which a bulk sample was taken. Filed with Proof of Claim.</p> <p>1/03/07 Gobbell Hays Partners, Inc. Report styled <i>Inspection of Asbestos-Containing Surface Treatment Materials</i> prepared by Wade Anderson that includes description of building, location and quantity of Grace ACM and hazard assessment for Grace ACM in this building. Filed as supplemental claims information.</p>

CLAIM #	ENTITY/BUILDING NAME	DESCRIPTION OF REPORT
		01/09/07 Expert Report by Martin R. Bennett, Materials Analytical Services, LLC, which includes Qualifications, Field Notes, Background and General Observations, AHERA Assessment, and Contamination Assessment for ACSTM in this building. The report also includes the results of micro-vacuum settled dust samples. This report has been filed as supplemental claims information with the Claims Facility.
12735	STATE OF ARKANSAS/ Arkansas State Hospital – Unit No. 4	<p>12/23/2002 Construction Inspectors, Inc. <i>Chain of Custody Log(s)</i> and <i>Bulk Sample Data Sheet(s)</i>, which includes the sample and material location, and a sample location of the area from which a bulk sample was taken. Filed with Proof of Claim.</p> <p>1/03/07 Gobbell Hays Partners, Inc. Report styled <i>Inspection of Asbestos-Containing Surface Treatment Materials</i> prepared by Wade Anderson that includes description of building, location and quantity of Grace ACM and hazard assessment for Grace ACM in this building. Filed as supplemental claims information.</p> <p>01/09/07 Expert Report by Martin R. Bennett, Materials Analytical Services, LLC, which includes Qualifications, Field Notes, Background and General Observations, AHERA Assessment, and Contamination Assessment for ACSTM in this building. The report also includes the results of micro-vacuum settled dust samples. This report has been filed as supplemental claims information with the Claims Facility.</p>
12731	STATE OF ARKANSAS/ Arkansas State Hospital – Unit No. 5	<p>12/23/2002 Construction Inspectors, Inc. <i>Chain of Custody Log(s)</i> and <i>Bulk Sample Data Sheet(s)</i>, which includes the sample and material location, and a sample location of the area from which a bulk sample was taken. Filed with Proof of Claim.</p> <p>1/03/07 Gobbell Hays Partners, Inc. Report styled <i>Inspection of Asbestos-Containing</i></p>

CLAIM #	ENTITY/BUILDING NAME	DESCRIPTION OF REPORT
		<i>Surface Treatment Materials</i> prepared by Wade Anderson that includes description of building, location and quantity of Grace ACM and hazard assessment for Grace ACM in this building. Filed as supplemental claims information.
12730	STATE OF ARKANSAS/ Arkansas State Hospital – Unit No. 6	<p>12/23/2002 Construction Inspectors, Inc. <i>Chain of Custody Log(s)</i> and <i>Bulk Sample Data Sheet(s)</i>, which includes the sample and material location, and a sample location of the area from which a bulk sample was taken. Filed with Proof of Claim.</p> <p>1/03/07 Gobbell Hays Partners, Inc. Report styled <i>Inspection of Asbestos-Containing Surface Treatment Materials</i> prepared by Wade Anderson that includes description of building, location and quantity of Grace ACM and hazard assessment for Grace ACM in this building. Filed as supplemental claims information.</p>
12679	STATE OF ARKANSAS/ Arkansas State Hospital – Vocational Shops (aka Maintenance Shop)	<p>12/31/2002 Construction Inspectors, Inc. <i>Chain of Custody Log(s)</i> and <i>Bulk Sample Data Sheet(s)</i>, which includes the sample and material location, and a sample location of the area from which a bulk sample was taken. Filed with Proof of Claim.</p> <p>1/03/07 Gobbell Hays Partners, Inc. Report styled <i>Inspection of Asbestos-Containing Surface Treatment Materials</i> prepared by Wade Anderson that includes description of building, location and quantity of Grace ACM and hazard assessment for Grace ACM in this building. Filed as supplemental claims information.</p> <p>01/09/07 Expert Report by Martin R. Bennett, Materials Analytical Services, LLC, which includes Qualifications, Field Notes, Background and General Observations, AHERA Assessment, and Contamination Assessment for ACSTM in this building. The report also includes the results of micro-vacuum settled dust samples. This report has been filed as</p>

CLAIM #	ENTITY/BUILDING NAME	DESCRIPTION OF REPORT
		supplemental claims information with the Claims Facility.
12675	STATE OF ARKANSAS/ Office of Child Support Enforcement (ARKLA Bldg.)	<p>Construction Inspectors, Inc. <i>Chain of Custody Log(s)</i> and <i>Bulk Sample Data Sheet(s)</i>, which includes the sample and material location, and a sample location of the area from which a bulk sample was taken. Filed with Proof of Claim.</p> <p>01/31/2006 Construction Inspectors, Inc. Report styled <i>Inspection of Asbestos-Containing Surface Treatment Materials</i> prepared by John Mertian that includes description of building, surveys of building, and location, types and quantity of ACM. Filed as supplemental claims information.</p> <p>1/9/2007 Gobbell Hays Partners, Inc. Report styled <i>Inspection of Asbestos-Containing Surface Treatment Materials</i> prepared by Wade Anderson that includes description of building, location and quantity of Grace ACM and hazard assessment for Grace ACM in this building. Filed as supplemental claims information.</p> <p>01/09/07 Expert Report by Martin R. Bennett, Materials Analytical Services, LLC, which includes Qualifications, Field Notes, Background and General Observations, AHERA Assessment, and Contamination Assessment for ACSTM in this building. The report also includes the results of micro-vacuum settled dust samples. This report has been filed as supplemental claims information with the Claims Facility.</p>
12674	STATE OF ARKANSAS/ Booneville Human Dev. Ctr. – Judge Joseph Hill Bldg.	<p>01/07/2003 Construction Inspectors, Inc. <i>Chain of Custody Log(s)</i> and <i>Bulk Sample Data Sheet(s)</i>, which includes the sample and material location, and a sample location of the area from which a bulk sample was taken. Filed with Proof of Claim.</p> <p>10/06/2006 Construction Inspectors, Inc. Report styled <i>Inspection of Asbestos-Containing Surface Treatment Materials</i> prepared by Tom</p>

CLAIM #	ENTITY/BUILDING NAME	DESCRIPTION OF REPORT
		Manning that includes description of building, surveys of building, and location, types and quantity of ACM. Filed as supplemental claims information.
12725	STATE OF ARKANSAS/ Conway Development Center – No. 25 Cedar	12/30/2002 Construction Inspectors, Inc. <i>Chain of Custody Log(s)</i> and <i>Bulk Sample Data Sheet(s)</i> , which includes the sample and material location, and a sample location of the area from which a bulk sample was taken. Filed with Proof of Claim.  10/06/2006 Construction Inspectors, Inc. Report styled <i>Inspection of Asbestos-Containing Surface Treatment Materials</i> prepared by John Mertian that includes description of building, surveys of building, and location, types and quantity of ACM. Filed as supplemental claims information.
12729	STATE OF ARKANSAS/ Conway Development Center – No. 28 Cedar	12/30/2002 Construction Inspectors, Inc. <i>Chain of Custody Log(s)</i> and <i>Bulk Sample Data Sheet(s)</i> , which includes the sample and material location, and a sample location of the area from which a bulk sample was taken. Filed with Proof of Claim.
12728	STATE OF ARKANSAS/ Conway Development Center – No. 29 Cedar	12/30/2002 Construction Inspectors, Inc. <i>Chain of Custody Log(s)</i> and <i>Bulk Sample Data Sheet(s)</i> , which includes the sample and material location, and a sample location of the area from which a bulk sample was taken. Filed with Proof of Claim.
12717	STATE OF ARKANSAS/ Conway Development Center – No. 3 Cedar	12/30/2002 Construction Inspectors, Inc. <i>Chain of Custody Log(s)</i> and <i>Bulk Sample Data Sheet(s)</i> , which includes the sample and material location, and a sample location of the area from which a bulk sample was taken. Filed with Proof of Claim.
12702	STATE OF ARKANSAS/ Conway Development Center – No. 30 Hickory	12/30/2002 Construction Inspectors, Inc. <i>Chain of Custody Log(s)</i> and <i>Bulk Sample Data Sheet(s)</i> , which includes the sample and material location, and a sample location of the area from which a bulk sample was taken. Filed with Proof of Claim.
12714	STATE OF ARKANSAS/ Conway Development Center – No. 5 Cedar	12/22/2002 Construction Inspectors, Inc. <i>Chain of Custody Log(s)</i> and <i>Bulk Sample Data Sheet(s)</i> , which includes the sample and material

CLAIM #	ENTITY/BUILDING NAME	DESCRIPTION OF REPORT
		location, and a sample location of the area from which a bulk sample was taken. Filed with Proof of Claim.  10/06/2006 Construction Inspectors, Inc. Report styled <i>Inspection of Asbestos-Containing Surface Treatment Materials</i> prepared by John Mertian that includes description of building, surveys of building, and location, types and quantity of ACM. Filed as supplemental claims information.
12701	STATE OF ARKANSAS/ Conway Development Center – 32 Poplar	12/30/2002 Construction Inspectors, Inc. <i>Chain of Custody Log(s)</i> and <i>Bulk Sample Data Sheet(s)</i> , which includes the sample and material location, and a sample location of the area from which a bulk sample was taken. Filed with Proof of Claim.
12719	STATE OF ARKANSAS/ Conway Development Center – Administration Building	12/22/2002 Construction Inspectors, Inc. <i>Chain of Custody Log(s)</i> and <i>Bulk Sample Data Sheet(s)</i> , which includes the sample and material location, and a sample location of the area from which a bulk sample was taken. Filed with Proof of Claim.  10/06/2006 Construction Inspectors, Inc. Report styled <i>Inspection of Asbestos-Containing Surface Treatment Materials</i> prepared by John Mertian that includes description of building, surveys of building, and location, types and quantity of ACM. Filed as supplemental claims information.
12724	STATE OF ARKANSAS/ Conway Development Center – Classroom No. 10	12/22/2002 Construction Inspectors, Inc. <i>Chain of Custody Log(s)</i> and <i>Bulk Sample Data Sheet(s)</i> , which includes the sample and material location, and a sample location of the area from which a bulk sample was taken. Filed with Proof of Claim.
12723	STATE OF ARKANSAS/ Conway Development Center – Classroom No. 3 & No. 5	12/22/2002 Construction Inspectors, Inc. <i>Chain of Custody Log(s)</i> and <i>Bulk Sample Data Sheet(s)</i> , which includes the sample and material location, and a sample location of the area from which a bulk sample was taken. Filed with Proof of Claim.
12722	STATE OF ARKANSAS/ Conway Development Center –	12/30/2002 Construction Inspectors, Inc. <i>Chain of Custody Log(s)</i> and <i>Bulk Sample Data</i>

CLAIM #	ENTITY/BUILDING NAME	DESCRIPTION OF REPORT
	Classroom No. 6 & No. 8	<p><i>Sheet(s)</i>, which includes the sample and material location, and a sample location of the area from which a bulk sample was taken. Filed with Proof of Claim.</p> <p>10/06/2006 Construction Inspectors, Inc. Report styled <i>Inspection of Asbestos-Containing Surface Treatment Materials</i> prepared by John Mertian that includes description of building, surveys of building, and location, types and quantity of ACM. Filed as supplemental claims information.</p>
12726	STATE OF ARKANSAS/ Conway Development Center – Classroom No. 7 & No. 9	<p>12/22/2002 Construction Inspectors, Inc. <i>Chain of Custody Log(s)</i> and <i>Bulk Sample Data Sheet(s)</i>, which includes the sample and material location, and a sample location of the area from which a bulk sample was taken. Filed with Proof of Claim.</p> <p>10/06/2006 Construction Inspectors, Inc. Report styled <i>Inspection of Asbestos-Containing Surface Treatment Materials</i> prepared by John Mertian that includes description of building, surveys of building, and location, types and quantity of ACM. Filed as supplemental claims information.</p>
12716	STATE OF ARKANSAS/ Conway Development Center – Residence No. 2	<p>12/22/2002 Construction Inspectors, Inc. <i>Chain of Custody Log(s)</i> and <i>Bulk Sample Data Sheet(s)</i>, which includes the sample and material location, and a sample location of the area from which a bulk sample was taken. Filed with Proof of Claim.</p> <p>10/06/2006 Construction Inspectors, Inc. Report styled <i>Inspection of Asbestos-Containing Surface Treatment Materials</i> prepared by John Mertian that includes description of building, surveys of building, and location, types and quantity of ACM. Filed as supplemental claims information.</p>
12718	STATE OF ARKANSAS/ Conway Development Center – SLT Office	<p>12/22/2002 Construction Inspectors, Inc. <i>Chain of Custody Log(s)</i> and <i>Bulk Sample Data Sheet(s)</i>, which includes the sample and material location, and a sample location of the area from which a bulk sample was taken. Filed with</p>

CLAIM #	ENTITY/BUILDING NAME	DESCRIPTION OF REPORT
		Proof of Claim.  10/06/2006 Construction Inspectors, Inc. Report styled <i>Inspection of Asbestos-Containing Surface Treatment Materials</i> prepared by John Mertian that includes description of building, surveys of building, and location, types and quantity of ACM. Filed as supplemental claims information.
12687	STATE OF ARKANSAS/ Employment Security Dept. 501 W. Arch	01/06/2003 Construction Inspectors, Inc. <i>Chain of Custody Log(s)</i> and <i>Bulk Sample Data Sheet(s)</i> , which includes the sample and material location, and a sample location of the area from which a bulk sample was taken. Filed with Proof of Claim.
12685	STATE OF ARKANSAS/ Finance & Administration Bldg.	12/20/2002 Construction Inspectors, Inc. <i>Chain of Custody Log(s)</i> and <i>Bulk Sample Data Sheet(s)</i> , which includes the sample and material location, and a sample location of the area from which a bulk sample was taken. Filed with Proof of Claim.
12691	STATE OF ARKANSAS/ Justice Building	12/20/2002 Construction Inspectors, Inc. <i>Chain of Custody Log(s)</i> and <i>Bulk Sample Data Sheet(s)</i> , which includes the sample and material location, and a sample location of the area from which a bulk sample was taken. Filed with Proof of Claim.
12673	STATE OF ARKANSAS/ Ledbetter Building	Construction Inspectors, Inc. <i>Chain of Custody Log(s)</i> and <i>Bulk Sample Data Sheet(s)</i> , which includes the sample and material location, and a sample location of the area from which a bulk sample was taken. Filed with Proof of Claim.
12688	STATE OF ARKANSAS/ SBS Building	Construction Inspectors, Inc. <i>Chain of Custody Log(s)</i> and <i>Bulk Sample Data Sheet(s)</i> , which includes the sample and material location, and a sample location of the area from which a bulk sample was taken. Filed with Proof of Claim.  11/29/2006 Construction Inspectors, Inc. Report styled <i>Limited Inspection Report of State Building Services Building, Little Rock, Arkansas</i> , prepared by Tom Manning and John Mertian that includes scope of inspection, background, description of inspections, and results of inspections.

CLAIM #	ENTITY/BUILDING NAME	DESCRIPTION OF REPORT
		<p>12/27/2006 Gobbell Hays Partners, Inc. Report styled <i>Inspection of Asbestos-Containing Surface Treatment Materials</i> prepared by Wade Anderson that includes description of building, location and quantity of Grace ACM and hazard assessment for Grace ACM in this building. Filed as supplemental claims information.</p> <p>01/09/07 Expert Report by Martin R. Bennett, Materials Analytical Services, LLC, which includes Qualifications, Field Notes, Background and General Observations, AHERA Assessment, and Contamination Assessment for ACSTM in this building. The report also includes the results of micro-vacuum settled dust samples. This report has been filed as supplemental claims information with the Claims Facility.</p>
12690	STATE OF ARKANSAS/ School for the Deaf – Wilbur Mills Library	<p>01/03/2003 Construction Inspectors, Inc. <i>Chain of Custody Log(s)</i> and <i>Bulk Sample Data Sheet(s)</i>, which includes the sample and material location, and a sample location of the area from which a bulk sample was taken. Filed with Proof of Claim.</p> <p>12/29/2006 Construction Inspectors, Inc. Report styled <i>Inspection of Asbestos-Containing Surface Treatment Materials</i> prepared by John Mertian that includes description of building, surveys of building, and location, types and quantity of ACM and hazard assessment. Filed as supplemental claims information.</p>
12727	STATE OF ARKANSAS/ Conway Development Center- Classroom No. 2 & No. 4	<p>12/22/2002 Construction Inspectors, Inc. <i>Chain of Custody Log(s)</i> and <i>Bulk Sample Data Sheet(s)</i>, which includes the sample and material location, and a sample location of the area from which a bulk sample was taken. Filed with Proof of Claim.</p> <p>10/06/2006 Construction Inspectors, Inc. Report styled <i>Inspection of Asbestos-Containing Surface Treatment Materials</i> prepared by</p>

CLAIM #	ENTITY/BUILDING NAME	DESCRIPTION OF REPORT
		John Mertian that includes description of building, surveys of building, and location, types and quantity of ACM. Filed as supplemental claims information.

**C. STATE OF CONNECTICUT**

CLAIM #	ENTITY/BUILDING NAME	DESCRIPTION OF REPORT
12681	STATE OF CONNECTICUT/ Connecticut Supreme Court Bldg.	<p>Construction Inspectors, Inc. <i>Chain of Custody Log(s)</i> and <i>Bulk Sample Data Sheet(s)</i>, which includes the sample and material location, and a sample location of the area from which a bulk sample was taken. Filed with Proof of Claim.</p> <p>12/06/2005 Construction Inspectors, Inc. Report styled <i>Inspection of Asbestos-Containing Surface Treatment Materials</i> prepared by John Mertian that includes description of building, surveys of building, and location, types and quantity of ACM. Filed as supplemental claims information.</p> <p>01/09/07 Expert Report by Martin R. Bennett, Materials Analytical Services, LLC, which includes Qualifications, Field Notes, Background and General Observations, AHERA Assessment, and Contamination Assessment for ACSTM in this building. The report also includes the results of micro-vacuum settled dust samples. This report has been filed as supplemental claims information with the Claims Facility.</p>

**D. STATE OF OKLAHOMA:**

CLAIM #	ENTITY/BUILDING NAME	DESCRIPTION OF REPORT
6953	STATE OF OKLAHOMA/ Central Oklahoma Comm. Mental Health Center – Building A	<p>Construction Inspectors, Inc. <i>Chain of Custody Log(s)</i> and <i>Bulk Sample Data Sheet(s)</i>, which includes the sample and material location, and a sample location of the area from which a bulk sample was taken. Filed with Proof of Claim.</p> <p>The surfacing ACM was friable and damaged, and has been removed from this building. The Asbestos Project Design documents regarding the removal and other related surveys and abatement documents were filed with the Proof</p>

CLAIM #	ENTITY/BUILDING NAME	DESCRIPTION OF REPORT
		<p>of Claim. The State of Oklahoma Department of Central Services - Asbestos Division or the State of Oklahoma's Correction Division - Asbestos Division was in charge of designing the project and removing the surfacing ACM. The State of Oklahoma's asbestos project designer or a representative from the State will testify as to the hazard assessment of the material and the damaged condition of the surfacing ACM.</p>
6954	STATE OF OKLAHOMA/ Central Oklahoma Comm. Mental Health Center – Building B	<p>12/10/2002 Construction Inspectors, Inc. <i>Chain of Custody Log(s)</i> and <i>Bulk Sample Data Sheet(s)</i>, which includes the sample and material location, and a sample location of the area from which a bulk sample was taken. Filed with Proof of Claim.</p> <p>The surfacing ACM was friable and damaged and has been removed from this building. The Asbestos Project Design documents regarding the removal and other related surveys and abatement documents were filed with the Proof of Claim. The State of Oklahoma Department of Central Services - Asbestos Division or the State of Oklahoma's Correction Division - Asbestos Division was in charge of designing the project and removing the surfacing ACM. The State of Oklahoma's asbestos project designer or a representative from the State will testify as to the hazard assessment of the material and the damaged condition of the surfacing ACM.</p>
6955	STATE OF OKLAHOMA/ Central Oklahoma Comm. Mental Health Center – Building C	<p>12/10/2002 Construction Inspectors, Inc. <i>Chain of Custody Log(s)</i> and <i>Bulk Sample Data Sheet(s)</i>, which includes the sample and material location, and a sample location of the area from which a bulk sample was taken. Filed with Proof of Claim.</p> <p>The surfacing ACM was friable and damaged and has been removed from this building. The Asbestos Project Design documents regarding the removal and other related surveys and abatement documents were filed with the Proof of Claim. The State of Oklahoma Department</p>

CLAIM #	ENTITY/BUILDING NAME	DESCRIPTION OF REPORT
		of Central Services - Asbestos Division or the State of Oklahoma's Correction Division - Asbestos Division was in charge of designing the project and removing the surfacing ACM. The State of Oklahoma's asbestos project designer or a representative from the State will testify as to the hazard assessment of the material and the damaged condition of the surfacing ACM.
6956	STATE OF OKLAHOMA/ Central Oklahoma Comm. Mental Health Center – Building D	<p>12/10/2002 Construction Inspectors, Inc. <i>Chain of Custody Log(s)</i> and <i>Bulk Sample Data Sheet(s)</i>, which includes the sample and material location, and a sample location of the area from which a bulk sample was taken. Filed with Proof of Claim.</p> <p>The surfacing ACM was friable and damaged, and has been removed from this building. The Asbestos Project Design documents regarding the removal and other related surveys and abatement documents were filed with the Proof of Claim. The State of Oklahoma Department of Central Services - Asbestos Division or the State of Oklahoma's Correction Division - Asbestos Division was in charge of designing the project and removing the surfacing ACM. The State of Oklahoma's asbestos project designer or a representative from the State will testify as to the hazard assessment of the material and the damaged condition of the surfacing ACM.</p>
5589	STATE OF OKLAHOMA/ Classen Building 1411	<p>08/26/2002 Construction Inspectors, Inc. <i>Chain of Custody Log(s)</i> and <i>Bulk Sample Data Sheet(s)</i>, which includes the sample and material location, and a sample location of the area from which a bulk sample was taken. Filed with Proof of Claim.</p> <p>The surfacing ACM was friable and damaged, and has been removed from this building. The Asbestos Project Design documents regarding the removal and other related surveys and abatement documents were filed with the Proof of Claim. The State of Oklahoma Department of Central Services - Asbestos Division or the</p>

CLAIM #	ENTITY/BUILDING NAME	DESCRIPTION OF REPORT
		State of Oklahoma's Correction Division - Asbestos Division was in charge of designing the project and removing the surfacing ACM. The State of Oklahoma's asbestos project designer or a representative from the State will testify as to the hazard assessment of the material and the damaged condition of the surfacing ACM.
5588	STATE OF OKLAHOMA/ Eddie Warrior Unit Auditorium & Programs Building	<p>12/11/2002 Construction Inspectors, Inc. <i>Chain of Custody Log(s)</i> and <i>Bulk Sample Data Sheet(s)</i>, which includes the sample and material location, and a sample location of the area from which a bulk sample was taken. Filed with Proof of Claim.</p> <p>The surfacing ACM was friable and damaged, and has been removed from this building. The Asbestos Project Design documents regarding the removal and other related surveys and abatement documents were filed with the Proof of Claim. The State of Oklahoma Department of Central Services - Asbestos Division or the State of Oklahoma's Correction Division - Asbestos Division was in charge of designing the project and removing the surfacing ACM. The State of Oklahoma's asbestos project designer or a representative from the State will testify as to the hazard assessment of the material and the damaged condition of the surfacing ACM.</p>
5587	STATE OF OKLAHOMA/ Griffin Memorial Hospital Activities Center, Bldg. 40	<p>12/10/2002 Construction Inspectors, Inc. <i>Chain of Custody Log(s)</i> and <i>Bulk Sample Data Sheet(s)</i>, which includes the sample and material location, and a sample location of the area from which a bulk sample was taken. Filed with Proof of Claim.</p> <p>The surfacing ACM was friable and damaged, and has been removed from this building. The Asbestos Project Design documents regarding the removal and other related surveys and abatement documents were filed with the Proof of Claim. The State of Oklahoma Department of Central Services - Asbestos Division or the State of Oklahoma's Correction Division -</p>

CLAIM #	ENTITY/BUILDING NAME	DESCRIPTION OF REPORT
		Asbestos Division was in charge of designing the project and removing the surfacing ACM. The State of Oklahoma's asbestos project designer or a representative from the State will testify as to the hazard assessment of the material and the damaged condition of the surfacing ACM.
5591	STATE OF OKLAHOMA/ Jess Dunn Correctional Unit – Bldg. 500	<p>12/11/2002 Construction Inspectors, Inc. <i>Chain of Custody Log(s)</i> and <i>Bulk Sample Data Sheet(s)</i>, which includes the sample and material location, and a sample location of the area from which a bulk sample was taken. Filed with Proof of Claim.</p> <p>The surfacing ACM was friable and damaged, and has been removed from this building. The Asbestos Project Design documents regarding the removal and other related surveys and abatement documents were filed with the Proof of Claim. The State of Oklahoma Department of Central Services - Asbestos Division or the State of Oklahoma's Correction Division - Asbestos Division was in charge of designing the project and removing the surfacing ACM. The State of Oklahoma's asbestos project designer or a representative from the State will testify as to the hazard assessment of the material and the damaged condition of the surfacing ACM.</p>
6967	STATE OF OKLAHOMA/ Mental Health & Substance Abuse Srvs. Building	<p>12/09/2002 Construction Inspectors, Inc. <i>Chain of Custody Log(s)</i> and <i>Bulk Sample Data Sheet(s)</i>, which includes the sample and material location, and a sample location of the area from which a bulk sample was taken. Filed with Proof of Claim.</p> <p>The surfacing ACM was friable and damaged, and has been removed from this building. The Asbestos Project Design documents regarding the removal and other related surveys and abatement documents were filed with the Proof of Claim. The State of Oklahoma Department of Central Services - Asbestos Division or the State of Oklahoma's Correction Division - Asbestos Division was in charge of designing</p>

CLAIM #	ENTITY/BUILDING NAME	DESCRIPTION OF REPORT
		the project and removing the surfacing ACM. The State of Oklahoma's asbestos project designer or a representative from the State will testify as to the hazard assessment of the material and the damaged condition of the surfacing ACM.
5590	STATE OF OKLAHOMA/ Western Hills Lodge	<p>11/12/2002 Construction Inspectors, Inc. <i>Chain of Custody Log(s)</i> and <i>Bulk Sample Data Sheet(s)</i>, which includes the sample and material location, and a sample location of the area from which a bulk sample was taken. Filed with Proof of Claim.</p> <p>The surfacing ACM was friable and damaged, and has been removed from this building. The Asbestos Project Design documents regarding the removal and other related surveys and abatement documents were filed with the Proof of Claim. The State of Oklahoma Department of Central Services - Asbestos Division or the State of Oklahoma's Correction Division - Asbestos Division was in charge of designing the project and removing the surfacing ACM. The State of Oklahoma's asbestos project designer or a representative from the State will testify as to the hazard assessment of the material and the damaged condition of the surfacing ACM.</p>
5592	STATE OF OKLAHOMA/ Wiley Post Historical Bldg.	<p>12/09/2002 Construction Inspectors, Inc. <i>Chain of Custody Log(s)</i> and <i>Bulk Sample Data Sheet(s)</i>, which includes the sample and material location, and a sample location of the area from which a bulk sample was taken. Filed with Proof of Claim.</p> <p>The surfacing ACM was friable and damaged, and has been removed from this building. The Asbestos Project Design documents regarding the removal and other related surveys and abatement documents were filed with the Proof of Claim. Representative from the Oklahoma Health Department will testify as to the hazard assessment of the material and the damaged condition of the surfacing ACM.</p>
8016	STATE OF OKLAHOMA/	01/16/2003 Construction Inspectors, Inc. <i>Chain</i>

CLAIM #	ENTITY/BUILDING NAME	DESCRIPTION OF REPORT
	Department of Health Headquarters	<p><i>of Custody Log(s) and Bulk Sample Data Sheet(s)</i>, which includes the sample and material location, and a sample location of the area from which a bulk sample was taken. Filed with Proof of Claim.</p> <p>The surfacing ACM was friable and damaged, and has been removed from this building. The Asbestos Project Design documents regarding the removal and other related surveys and abatement documents were filed with the Proof of Claim. The State of Oklahoma Department of Central Services - Asbestos Division or the State of Oklahoma's Correction Division - Asbestos Division was in charge of designing the project and removing the surfacing ACM. The State of Oklahoma's asbestos project designer or a representative from the State will testify as to the hazard assessment of the material and the damaged condition of the surfacing ACM.</p>

**E. CITY OF AMARILLO, TEXAS:**

CLAIM #	ENTITY/BUILDING NAME	DESCRIPTION OF REPORT
5661	CITY OF AMARILLO, TX – Amarillo International Airport	<p>Construction Inspectors, Inc. <i>Chain of Custody Log(s) and Bulk Sample Data Sheet(s)</i>, which includes the sample and material location, and a sample location of the area from which a bulk sample was taken. Filed with Proof of Claim.</p> <p>01/09/2007 Gobbell Hays Partners, Inc. Report styled <i>Inspection of Asbestos-Containing Surface Treatment Materials</i> prepared by Wade Anderson that includes description of building, location and quantity of Grace ACM and hazard assessment for Grace ACM in this building. Filed as supplemental claims information.</p> <p>01/09/07 Expert Report by Martin R. Bennett, Materials Analytical Services, LLC, which includes Qualifications, Field Notes, Background and General Observations, AHERA Assessment, and Contamination Assessment for ACSTM in this building. The report also</p>

CLAIM #	ENTITY/BUILDING NAME	DESCRIPTION OF REPORT
		includes the results of micro-vacuum settled dust samples. This report has been filed as supplemental claims information with the Claims Facility.
5656	CITY OF AMARILLO, TX – Bivins Building	<p>Construction Inspectors, Inc. <i>Chain of Custody Log(s)</i> and <i>Bulk Sample Data Sheet(s)</i>, which includes the sample and material location, and a sample location of the area from which a bulk sample was taken. Filed with Proof of Claim.</p> <p>01/09/2007 Gobbell Hays Partners, Inc. Report styled <i>Inspection of Asbestos-Containing Surface Treatment Materials</i> prepared by Wade Anderson that includes description of building, location and quantity of Grace ACM and hazard assessment for Grace ACM in this building. Filed as supplemental claims information.</p> <p>01/09/07 Expert Report by Martin R. Bennett, Materials Analytical Services, LLC, which includes Qualifications, Field Notes, Background and General Observations, AHERA Assessment, and Contamination Assessment for ACSTM in this building. The report also includes the results of micro-vacuum settled dust samples. This report has been filed as supplemental claims information with the Claims Facility.</p>

**F. CITY OF HOUSTON, TEXAS:**

CLAIM #	ENTITY/BUILDING NAME	DESCRIPTION OF REPORT
6968	CITY OF HOUSTON, TX – Police Department Bldg. (1200 Travis)	<p>Construction Inspectors, Inc. <i>Chain of Custody Log(s)</i> and <i>Bulk Sample Data Sheet(s)</i>, which includes the sample and material location, and a sample location of the area from which a bulk sample was taken. Filed with Proof of Claim.</p> <p>01/13/07 Construction Inspectors, Inc. Report styled <i>Inspection of Asbestos-Containing Surface Treatment Materials</i> prepared by Kenneth Pigg that includes description of building, surveys of building, and location, types and quantity of ACM, and hazard assessment. Filed as supplemental claims</p>

CLAIM #	ENTITY/BUILDING NAME	DESCRIPTION OF REPORT
		information.
6969	CITY OF HOUSTON, TX – Public Works Bldg. (611 Walker)	<p>Construction Inspectors, Inc. <i>Chain of Custody Log(s)</i> and <i>Bulk Sample Data Sheet(s)</i>, which includes the sample and material location, and a sample location of the area from which a bulk sample was taken. Filed with Proof of Claim.</p> <p>01/13/07 Construction Inspectors, Inc. Report styled <i>Inspection of Asbestos-Containing Surface Treatment Materials</i> prepared by Kenneth Pigg that includes description of building, surveys of building, and location, types and quantity of ACM, and hazard assessment. Filed as supplemental claims information.</p> <p>01/09/07 Expert Report by Martin R. Bennett, Materials Analytical Services, LLC, which includes Qualifications, Field Notes, Background and General Observations, AHERA Assessment, and Contamination Assessment for ACSTM in this building. The report also includes the results of micro-vacuum settled dust samples. This report has been filed as supplemental claims information with the Claims Facility.</p>

**G. COLEMAN HOUSING AUTHORITY:**

CLAIM #	ENTITY/BUILDING NAME	DESCRIPTION OF REPORT
5658	COLEMAN HOUSING AUTHORITY – High Rise Bldg.	<p>Construction Inspectors, Inc. <i>Chain of Custody Log(s)</i> and <i>Bulk Sample Data Sheet(s)</i>, which includes the sample and material location, and a sample location of the area from which a bulk sample was taken. Filed with Proof of Claim.</p> <p>09/19/2006 Construction Inspectors, Inc. Report styled <i>Inspection of Asbestos-Containing Surface Treatment Materials</i> prepared by Kenneth Pigg that includes description of building, surveys of building, and location, types and quantity of ACM. Filed as supplemental claims information.</p>

**H. EL PASO COUNTY, TEXAS:**

<b>CLAIM #</b>	<b>ENTITY/BUILDING NAME</b>	<b>DESCRIPTION OF REPORT</b>
5657	EL PASO COUNTY, TX – Landmark Building	<p>Construction Inspectors, Inc. <i>Chain of Custody Log(s)</i> and <i>Bulk Sample Data Sheet(s)</i>, which includes the sample and material location, and a sample location of the area from which a bulk sample was taken. Filed with Proof of Claim.</p> <p>09/19/2006 Construction Inspectors, Inc. Report styled <i>Inspection of Asbestos-Containing Surface Treatment Materials</i> prepared by Kenneth Pigg that includes description of building, surveys of building, and location, types and quantity of ACM. Filed as supplemental claims information.</p>

**I. HARLINGEN HOUSING AUTHORITY:**

<b>CLAIM #</b>	<b>ENTITY/BUILDING NAME</b>	<b>DESCRIPTION OF REPORT</b>
5659	HARLINGEN HOUSING AUTHORITY – Heritage Manor	<p>Construction Inspectors, Inc. <i>Chain of Custody Log(s)</i> and <i>Bulk Sample Data Sheet(s)</i>, which includes the sample and material location, and a sample location of the area from which a bulk sample was taken. Filed with Proof of Claim.</p> <p>01/07/07 Construction Inspectors, Inc. Report styled <i>Inspection of Asbestos-Containing Surface Treatment Materials</i> prepared by John Mertian that includes description of building, surveys of building, and location, types and quantity of ACM. Filed as supplemental claims information.</p>

**J. SABINE RIVER AUTHORITY OF TEXAS:**

<b>CLAIM #</b>	<b>ENTITY/BUILDING NAME</b>	<b>DESCRIPTION OF REPORT</b>
5660	SABINE RIVER AUTHORITY OF TEXAS – Iron & Bridge Division Office	<p>Construction Inspectors, Inc. <i>Chain of Custody Log(s)</i> and <i>Bulk Sample Data Sheet(s)</i>, which includes the sample and material location, and a sample location of the area from which a bulk sample was taken. Filed with Proof of Claim.</p> <p>01/10/07 Construction Inspectors, Inc. Report styled <i>Inspection of Asbestos-Containing Surface Treatment Materials</i> prepared by Kenneth Pigg that includes description of</p>

CLAIM #	ENTITY/BUILDING NAME	DESCRIPTION OF REPORT
		building, surveys of building, and location, types and quantity of ACM. Filed as supplemental claims information.

**K. CITY OF PHOENIX, ARIZONA:**

CLAIM #	ENTITY/BUILDING NAME	DESCRIPTION OF REPORT
5654	CITY OF PHOENIX, AZ – Civic Center North Plaza & Parking Garage	<p>Construction Inspectors, Inc. <i>Chain of Custody Log(s)</i> and <i>Bulk Sample Data Sheet(s)</i>, which includes the sample and material location, and a sample location of the area from which a bulk sample was taken. Filed with Proof of Claim.</p> <p>09/19/06 Construction Inspectors, Inc. Report styled <i>Survey of Asbestos-Containing Materials</i> by Kenneth Pigg that includes description of building, surveys of building, location, types and quantity of ACM and hazard assessment. Filed as supplemental claims information.</p>
5653	CITY OF PHOENIX, AZ – Multi Center Waste Treatment Plant – Digester Control #1	<p>Construction Inspectors, Inc. <i>Chain of Custody Log(s)</i> and <i>Bulk Sample Data Sheet(s)</i>, which includes the sample and material location, and a sample location of the area from which a bulk sample was taken. Filed with Proof of Claim.</p> <p>12/18/2006 Gobbell Hays Partners, Inc. Report styled <i>Inspection of Asbestos-Containing Surface Treatment Materials</i> prepared by Wade Anderson that includes description of building, location and quantity of Grace ACM and hazard assessment for Grace ACM in this building. Filed as supplemental claims information.</p>
5652	CITY OF PHOENIX, AZ – Multi Center Waste Treatment Plant – Maintenance Shop	<p>Construction Inspectors, Inc. <i>Chain of Custody Log(s)</i> and <i>Bulk Sample Data Sheet(s)</i>, which includes the sample and material location, and a sample location of the area from which a bulk sample was taken. Filed with Proof of Claim.</p> <p>12/18/2006 Gobbell Hays Partners, Inc. Report styled <i>Inspection of Asbestos-Containing Surface Treatment Materials</i> prepared by Wade Anderson that includes description of building, location and quantity of Grace ACM and hazard assessment for Grace ACM in this building. Filed as supplemental claims information.</p>

CLAIM #	ENTITY/BUILDING NAME	DESCRIPTION OF REPORT
		information.
5655	CITY OF PHOENIX, AZ – Sky Harbor Airport – Terminal 2	<p>Construction Inspectors, Inc. <i>Chain of Custody Log(s)</i> and <i>Bulk Sample Data Sheet(s)</i>, which includes the sample and material location, and a sample location of the area from which a bulk sample was taken. Filed with Proof of Claim.</p> <p>1/09/07 Gobbell Hays Partners, Inc. Report styled <i>Inspection of Asbestos-Containing Surface Treatment Materials</i> prepared by Wade Anderson that includes description of building, location and quantity of Grace ACM and hazard assessment for Grace ACM in this building. Filed as supplemental claims information.</p> <p>01/09/07 Expert Report by Martin R. Bennett, Materials Analytical Services, LLC, which includes Qualifications, Field Notes, Background and General Observations, AHERA Assessment, and Contamination Assessment for ACSTM in this building. The report also includes the results of micro-vacuum settled dust samples. This report has been filed as supplemental claims information with the Claims Facility.</p>
6102	CITY OF PHOENIX, AZ – FAA Tracon Building	Construction Inspectors, Inc. <i>Chain of Custody Log(s)</i> and <i>Bulk Sample Data Sheet(s)</i> , which includes the sample and material location, and a sample location of the area from which a bulk sample was taken. Filed with Proof of Claim.
5651	CITY OF PHOENIX, AZ – Squaw Peak Water Treatment Plant – Administration Bldg. #1	Construction Inspectors, Inc. <i>Chain of Custody Log(s)</i> and <i>Bulk Sample Data Sheet(s)</i> , which includes the sample and material location, and a sample location of the area from which a bulk sample was taken. Filed with Proof of Claim.
6065	CITY OF PHOENIX, AZ – Symphony Hall	<p>Construction Inspectors, Inc. <i>Chain of Custody Log(s)</i> and <i>Bulk Sample Data Sheet(s)</i>, which includes the sample and material location, and a sample location of the area from which a bulk sample was taken. Filed with Proof of Claim.</p> <p>09/20/2006 Construction Inspectors, Inc. Report styled <i>Inspection of Asbestos-Containing Surface Treatment Materials</i> prepared by</p>